


Cryogenic spares

Cernox™ 1050-Sd-ht Temperature Sensor



The Cernox™ 1050 resistance sensor is the standard sensor for use in magnetic fields up to 20 tesla as it has a very small magnetic field dependency.

The sensor is recommended for situations where reduced size or a fast thermal response time is needed.

